



sign	Socket	Specific No	Interface Description	Function
P3	J4	1	IR-CUT	IR-CUT
		2	IR-CUT	IR-CUT
P5	J40	1	GND	GND
		2	AC_IN	Audio input
		3	AC_OUT	Audio output
P2	J41	1	IRIN	Infrared light signal control
		2	GPIO2_0	Infrared light control
P4	J44	1	GND	GND
		2	UART0_RXD	Debug Serial port accept
		3	UART0_TXD	DebugSerial port send
		4	UART1_RXD	Serial port accept
		5	UART1_TXD	Serial port send
		6	W_LED	White light control
P1	J1	1	ACT_LED	Indicator light
		2	STA_LED	Indicator light
		3	ETHTX+	ETHTX+
		4	ETHTX-	ETHTX-
		5	ETHRX+	ETHRX+
		6	ETHRX-	ETHRX-
		7	GND	GND
		8	+12V	12V input